

# GEROfit® R

More protection – more safety

## 3. Installation guideline

These general installation instructions apply to buried PE-HD pipes according to DIN 8074/8075. They are complementary to existing specific standards and guidelines of DIN, DWA, DVGW, DIN CERTCO, DVS and KRV. Especially, for the jointing techniques, it is necessary also to adhere to the separate instructions issued by each of the different joint manufacturers.

PE-HD pipes and pipelines shall be processed and laid by well-trained specialist staff only. Installation work for gas and potable water supply shall be performed only by pipeline installation companies having a DVGW certificate according to DVGW Worksheet GW 301 – DVGW procedure for the certification of pipeline companies.

Construction work must be performed by installers having completed a training course according to DVGW Worksheet GW 330 – Welding of PE-HD pipes and pipeline components for gas and water mains; teaching and test plan. The activities need to be supervised by welding engineers according to the DVGW Worksheet GW 331 – Weld supervision for welding on PE pipelines for gas and water supply; teaching and test plan. The rules of accident prevention of the employers insurance liability company shall be observed during installation. The road traffic regulations are of special importance for any work within traffic zones; the guidelines for safety measures at roadworks sites shall be adhered to. The limits of use and performance of each product shall be observed.

### 3.1 Handling

PE-HD plastic pipes are transported in the form of straight lengths, coiled bundles or reels. They shall be properly handled, loaded and unloaded.

Upon delivery or just before the installation, an optical inspection of the pipe shall be carried out according to DVGW G 472, W 400-2, or DIN EN 805. Also, the information printed on the pipe shall be checked and the jointing zones shall be cleaned. Damaged parts will be discarded. Cuts can be made with a fine-toothed saw or a plastic pipe cutter. Guided saws, e.g. mitre boxes, allow cuts perpendicular to the pipe axis. Burrs and irregularities along the parting planes shall be removed with a suitable tool, e.g. a blade or scraper knife. The pipe ends need to be treated according to the jointing technique.

Dirt or incrustations on the inner faces and damages in general shall be prevented. Therefore, the end caps shall be removed only when the pipe components are installed.


Pipes shall not be dragged along ground or floors. Scoring, scratches or surface abrasions up to 10 % of the minimum wall

thickness in PE80 and PE100 pipes are tolerable. Pipes with more severe damage are not allowed to be installed (DVGW Worksheet W 400-2/September 2004). Also, lasting deformation of the pipes must be prevented. The storage area should be level and free of stones or sharp-edged objects.


Black PE-HD pipes are sufficiently protected from UV radiation due to their very nature (increased carbon black content in the material). They remain safe even after a longer time/several years of storage in the open air.

Coloured PE-HD pipes (e.g. yellow orange, royal blue) must be subjected to a usability check if exposed to radiation of 7.0GJ/m<sup>2</sup>, which is equivalent to two years of non-protected storage with direct sunlight exposure in Germany. The manufacturer can validate and release the pipes for further use.

The pipes shall be protected from contact with substances that are detrimental to PE (→ Technical Information, p. 61 et seq.).



4.17 Correct storage of GEROfit®R straight pipes without wooden framework



4.18 Correct storage of GEROfit®R pipe coils

## Product-specific instructions

### PE pipes in straight lengths

During transport, handling and storage, straight pipes should be supported substantially along their entire length and secured from rolling apart. Furthermore, appropriate retainers will prevent non-palletised pipes from rolling to the sides, for which purpose the pipe stack shall be arranged in straight and staggered layers. The maximum allowable stack height is 1.5 m (SDR classes  $\geq 26$  minus 0.5 m).

**! Thin-walled pipes of the classes SDR 21 to 33 shall be protected from direct sunlight (e.g. with white tarpaulin or fleece) to mitigate the risks of deflection and deformation.**

### PE-pipes in coils

Coiled pipe bundles shall be stored in horizontal position or in suitable racks. The holding straps or bands shall not be removed until immediately before installation.

The information labelled on the coils shall be adhered to.

### PE pipes wound on reels


Reels (drums) – especially the Gerodur large-reel system – shall be handled in compliance with the safety and handling instructions attached to them.

Improper handling of reels presents a risk to human health and equipment integrity. For **loading and unloading with a crane** it is therefore necessary to use appropriate spreader bars preventing any damage to the reel and pipe.


If **fork lift trucks** are used, they need to be equipped with specific attachments for reels.

Reels are not allowed to be stacked in storage. They shall be stored in vertical position and secured from rolling. Advantageously, storage areas should have a hard level surface.


Thermal expansion/contraction needs to be taken into account for cutting and laying the pipes. A rise in temperature will cause an increase in the length of the pipe. A drop in temperature causes a PE pipe to shorten by 0.2 mm per metre and K (→ Technical Information, p. 46).



4.19 Loading and unloading of reels with a crane



4.20 Handling of reels with a fork lift truck




4.21 Correct storage of large-size reels

## Unwinding


There are several ways how to uncoil pipes. In general, pipes having an outside diameter up to 63 mm are uncoiled in a vertical position. It is important to restrain the pipe ends when removing the holding straps or bands; otherwise, the pipe end might uncoil with extreme whipping force, especially in case of larger pipe diameters. Therefore, special care is required at this point (danger of accident!). It is wise to use an uncoiling aid. Coiled pipes lying on a wooden or steel carousel can be unwound in a straight line either by hand or via a slowly operating vehicle. Sharp bends (kinks) or spiral unwinding must be prevented.

During uncoiling, it is important to bear in mind that the degree of flexibility of PE pipes depends on ambient temperature. In case of near-frost temperatures pipes with a diameter of 75 mm or higher should, where possible, be warmed up while still in coil, e.g. with hot steam (max. 100 °C).

For unwinding pipes on the construction site, a suitable reel handling vehicle or other appropriate equipment should be used (e.g. transporters by BAGELA Baumaschinen GmbH & Co. KG).



4.22 Carousel-style decoiler



4.23 Caution: Whipping pipe end after removal of straps

## Processing

- GEROfit®R protection jacket pipes are weldable by butt fusion (→ jointing technologies, p. 140 et seq.) without prior removal of the additive protection layer made of polyolefin compound. Welding shall comply with the codes of practice of DVS. Subsequent application of a weld protective system (e.g. self-fusing seal tape) is not required (→ GEROfit®R, p. 123 et seq.).
- For welding the jacketed pipe with fittings, electrofusion fittings (→ jointing technologies, p. 143 et seq.), saddles, standard pipes, PE multilayer pipes with integrated protective layers and jacketed pipes of other manufacturers, it is necessary to remove the protection jacket in the welding area (→ handling of jacket peelers, p. 147 et seq.). In specific project cases, this can be done in the factory by Gerodur (to customer specifications). Then there will be no need for covering the weld afterwards in open construction or low-dig ploughing and milling operations. For trenchless techniques (e.g. pipe bursting, important: also for rocket plough), it is imperative to provide suitable circumferential protection flush with the outer contour.
- Therefore, it is necessary to select appropriate clamp sizes (larger than the core pipe diameter) in butt fusion welding. → table 4.26
- Pulling heads shall be long enough to provide appropriate protection for the jacket.



4.24 Pulling head put on the jacketed pipe (incl. jacket thickness)



4.25 Gerodur service: provision of project-specific clamps for butt fusion (Widos) – delivery in robust heavy-duty box

- The maximum allowable tensile forces (→ Technical information, p. 59) shall not be exceeded to avoid lasting damage to the pipeline.
- The pull-in operation inclusive of its parameters (tensile forces) shall be reported.
- The bending radius shall not fall below the allowable limit (→ Technical information, p. 58).
- It is not technologically possible to install GEROfit®R according to the close-fit method.

Dedicated special clamps for welding machines are available from Gerodur. → Accessories, p. 309.

Core pipe according to DIN 8074 DN/OD [mm]	Clamp size for GEROfit®R protection jacket pipes [mm]
25	26.6
32	34.4
40	42.4
50	52.4
63	65.7
75	78.0
90	93.1
110	113.6
125	128.9
140	144.2
160	164.7
180	186.5
200	206.6
225	231.8
250	256.9
280	288.7
315	323.9
355	364.2
400	412.4
450	462.7
500	513.0
560	573.4
630	643.8
Subject to production tolerances	

4.26 Core pipe diameters of GEROfit®R protection jacket pipes with the related clamp sizes.

## 3.2 Installation

### Trenching

#### Construction of pipe trench

The pipe trench shall be constructed according to DIN 4124. The backfill soil shall be assessed according to ZTV A-StB and DIN 18196. Installation work in public spaces is governed by DIN 1998.

The applicable standards and codes of practice are DIN EN 805 and DVGW W 400-2 for water service piping systems; DIN EN 1610 and DWA-A 139 for drains and sewers; DIN EN 12007-2 and DVGW G 472 for gas mains.

Application	Potable water	Gas	Sewage
Recommended height zone h in built-up areas	0.9m to 1.8m, depending on climate and soil conditions	0.6m to 1.3m (typical: max. 2.0m; front yards and pavements: 0.5m)	Min. 2.0m

4.27 Application-specific installation depths according to DVGW W 400-1

DN/OD [mm]	Minimum trench width $b (d_n + x)$ [m]			
	Sheeted trench		Non-sheeted (sloped) trench	
	Typical	Bracing	$\beta > 60^\circ$	$\beta \leq 60^\circ$
$\leq 400$	$d_n + 0.4$	$d_n + 0.7$	$d_n + 0.4$	$d_n + 0.4$
$> 400$	$d_n + 0.7$	$d_n + 0.7$	$d_n + 0.7$	$d_n + 0.4$

4.28 Trench width as a function of pipe size and slope angle according to DIN 4124

The minimum trench width  $b$  shall be the higher of the values depending on the nominal diameter (DN/OD) and the trench depth  $(h + d_n)$ .

**The values for the minimum trench width in the table at right do not apply for drains and sewers, which are governed by DIN EN 1610.**

For the values for  $d_n + x$ ,  $0.5x$  is equivalent to the minimum working space between pipe and trench wall or trench sheeting according to DIN 4124. The trench bottom shall be constructed so as to evenly support the pipeline.

**Bedding and backfill**


GEROfit®R protection jacket pipes with a core pipe made of PE 100-RC are suitable for installations without sand bedding due to their high resistance to slow crack growth as proven by an independent accredited testing institute. This implies less work and cost for excavation and replacement of in-situ ground with bedding sand according to DIN EN 805 (transport and landfill). The pipe characteristics require no grain size restrictions for bedding and backfill materials. Installation work in the public space (e.g. roadworks) must be in compliance with further requirements, standards and guidelines:

- DIN V ENV 1046
- DIN EN 805
- DIN 4124
- DIN EN ISO 14688
- DIN 18123
- ZTV A-StB
- DIN 18196
- ZTV E-StB

Depth of backfill cover $h + d_n$ [m]	Minimum trench width $b$ [m]	
$\leq 1.75$	sloped 0.6	sheeted 0.7
$> 1.75$ to $\leq 4.0$	0.8	
$> 4.0$	1.0	

4.29 Trench width as a function of pipe diameter and backfill cover according to DIN 4124

The backfill cover shall be selected so as to ensure the pipeline is buried below the frost line, depending on climate and soil conditions. The recommended depth of cover for agricultural lands is no less than 1.2 m.



4.30 Pipe trench – open construction

- DN/OD...nominal size as referred to the outside diameter [mm]
- $d_n$  .....nominal outside diameter [m]
- $\beta$  .....slope (angle) of the non-sheeted trench [°]
- $b$  .....minimum trench width [m]
- $h$  .....height zone [m]

**Low-dig and no-dig (trenchless) installation**

Trenchless installation techniques cause higher stress and loads than the conventional open-trench construction of a pipeline. GEROfit®R pipelines meet all requirements for sandless and trenchless installations on a properly tested and verified basis.

Installers must comply with the worksheets DVGW W 400-2 and G 472 and the DVGW method instructions for the different trenchless laying techniques to maintain constant quality standards:

- Relining (rehabilitation) according to DVGW GW 320
- Controllable horizontal directional drilling according to DVGW GW 321

- No-dig replacement using pushing or pulling procedures according to DVGW GW 322
  - No-dig renewal by pipe bursting procedure according to DVGW GW 323
  - No-dig construction types for gas and water connection lines according to DVGW GW 325 (non-finalised draft)
- This includes the installation of new pipes by ploughing and milling (low-dig) procedures, because the furrows and narrow trenches thus created are no conventional pipe trenches as defined in DIN 4124.
- Milling and ploughing procedures according to DVGW GW 324

Trenchless pipeline installation operations require extensive planning and design. It is necessary to conduct a preliminary assessment of the existing piping structures or subsoil conditions to select then the installation procedure, the appropriate pipe, the pipe joint and the other parameters.

Pipeline construction companies qualified according to DVGW GW 301 need the additional qualification R (rehabilitation) or GN (no-dig installation). A qualification according to DVGW GW 302 is sufficient for companies performing trenchless procedures without disruption or start-up of service and without connection or reconnection work during continued service. Trenchless pipe installation shall be recorded in a traceable documentation (including material certificates, test report with tensile forces, leak testing, CCTV inspection and other relevant processes).

#### Introduction of GEROfit®R protection jacket pipes

The dimensions of the access pit vary according to the laying method. Generally, the bending radius of the pipe shall not fall below the respective allowable minimum – but short-term deviation is considered not to be critical. Kinking of the pipe must be prevented.

The length of the access pit [m] results from:

1.31

$$L = \sqrt{H \times (4 \times R - H)}$$


For smaller pipe diameters, the pit dimensions can be reduced by lifting the pipe according to the following formula:

1.32


$$L^* = \sqrt{H \times (2 \times R - H)}$$

- L.....length of access pit [m]  
 L\*.....reduced length of access pit [m]  
 H.....pipe bottom depth [m]  
 R.....allowable bending radius [m]  
 WP.....turning point  
 WP\* .....possible turning point at smaller  
           pipe dimensions (e. g. up to DN 300)  
 d<sub>n</sub> .....nominal outside diameter [mm]

Allowable bending radius:  $R = 20 \times d_n$  at 20°C  
 → Technical information, p. 58



4.31 Determination of introduction lengths for GEROfit®R protection jacket pipe



4.32 Introduction of GEROfit®R protection jacket pipe from coil or large-size reel


**Milling and ploughing (DVGW GW 324)**

These installation methods are typically used in rural areas and outside traffic zones. In both techniques it is important to adhere to the allowable bending radii and tensile forces of the piping system being laid (DVGW requirements).


**Milling** (narrow trenching) is an open-cut method for mechanically cutting a narrow trench into ground while placing the GEROfit®R pipe at the same time onto the bottom of the trench. In most cases, the process produces a non man-entry trench and uses a laying box as temporary sheeting. The trench

needs no sand bedding and can thus be mechanically back-filled, and compacted, with compactable material removed during the cutting process.

**Ploughing** is a minimum-dig method for displacing soft ground with a plough blade and placing the GEROfit®R piping via a laying box onto the bottom of the furrow thus produced. The method can achieve installation rates of up to four kilometres per day, depending on soil class, pipe diameter, installation depth and equipment used.




6.33 Narrow trenching | 1 trench bottom | 2 backfill and compaction unit | 3 axial screw conveyors | 4 compactor | 5 laying box | 6 laser receiver | 7 utility marking tape | 8 milling disc or cutter chain | 9 GEROfit®R jacket pipe | 10 trenching and laying unit | 11 extracted material (spoil) | 12 piping guides



6.34 Ploughing | 1 GEROfit®R jacket pipe | 2 utility marking tape | 3 laying box | 4 plough blade | 5 plough | 6 pulling cable | 7 support | 8 cable winch | 9 winch truck | 10 piping guide

### Soil displacement method


The soil displacement technique is an economical and proven procedure best suited for the construction of house laterals and used worldwide for three decades already. An air-operated displacement hammer, also known as "rocket", is driven through the ground to create an underground void into which the GEROfit®R protection jacket pipes are introduced. There is no need to dig up or destroy existing surface structures or spaces like yards, gardens or traffic zones. Traffic will not be disrupted, and time and money can be saved for larger construction projects.



4.35 Soil displacement

### Directional drilling method


The installation of a new pipeline according to the directional drilling method is performed in three consecutive steps. The first step is the localisation-controlled boring of a continuous pilot hole, which defines the pipe route. Then the pilot hole is enlarged to the diameter required for the introduction of the GEROfit®R protection jacket pipe (reaming). In the third step, the butt fusion-jointed thrust-resistant piping is introduced into the enlarged hole. The execution of the works must be supervised by an engineer according to DVGW GW 329. The buckling strength of the pipeline must be higher than the maximum pressure of the drilling fluid.



4.36 Directional drilling

### Pipe bursting method


Pipe bursting is a structural renovation method for the renewal of an existing pipeline along its existing route. The old pipe is destroyed by the bursting head and the remaining pipe debris are pressed into the surrounding ground. The butt fusion-jointed thrust-resistant GEROfit®R piping is installed in the void thus created. The external bead of the welded joint must be removed for this purpose. The new pipe can have a larger diameter than the old one. The newly installed pipeline must be dimensioned to withstand the internal pressure or buckling pressure. → Technical information, p. 56



4.37 Pipe bursting

### Relining method

The relining method with annular space uses the existing pipe as a host pipe into which the butt fusion-jointed thrust-resistant GEROfit®R piping of reduced cross-section is introduced with the help of an installation device. The external and internal beads of the weld joint can be removed prior to installation. The annulus between the host pipe and the GEROfit®R pipe can be filled afterwards. The entire host pipe must meet the structural strength requirements. The liner pipe must be dimensioned to withstand the internal pressure or buckling pressure. → Technical information, p. 56



4.38 Relining

The allowable bending radii and tensile forces must be adhered to in all methods. → Technical information, p. 58 et seq.

### 3.3 Jointing technologies

GEROfit®R protection jacket pipes can be joined by means of appropriate jointing technologies according to the generally accepted engineering rules known for PE-HD pipes to form a pressure-sealed leak-free piping system.

The following table shows some of the common and recommended technologies for thrust-resistant pipe end-to-end and pipe-to-fitting joints according to current standards and guidelines.

Jointing method	Friction-locked/ detachable	Firmly bonded
Clamped, bolted, socket or pressed joints	✓	
Flange joints	✓	
Butt fusion		✓
Electrofusion (fittings)		✓

4.39 Categories of jointing techniques

Welding shall meet the following requirements for PE-HD pipes:

- Qualification of welders according to DVGW GW 330 or DVS 2212-1
- Execution of works according to DVS 2207-1 and use of equipment according to DVS 2208-1
- Supervision of welding operations according to DVGW GW 331 or DVS 2212-1 (Supplement 1)

When using mechanical jointing systems – clamped, bolted or socket joints – or welding fittings, it is generally necessary to remove the protection jacket from the core pipe in the jointing zone (peeling). This is also true for welding GEROfit®R with jacketed pipes of other manufacturers and for welding GEROfit®R with standard PE100/PE100-RC pipes. This operation requires appropriate tools, e.g. the jacket peeler GEROfit®pocket or pocket XL within the GEROfit® accessories programme (→ Accessories, p. 309).

Gerodur application engineers are available at all times to assist.

#### Butt fusion welding (HS)

The fusion ends of the pipes or pipe components to be joined are matched with a heater plate (initial bead-up phase), then heated to welding temperature at reduced pressure (heat-soak phase) and, after removal of the heater plate (changeover phase), joined under pressure (fusion jointing). The manufacturer’s information and instructions shall be observed.

This is where GEROfit®R protection jacket pipes offer special advantages:


- No need to peel off the protection jacket in butt fusion welding
- No subsequent weld protection required
- Where required (e.g. in pipe bursting), external weld bead can be easily removed (by cutting and stripping without special tools)

GEROfit®R protection jacket pipes are approved for butt fusion welding under the guidelines of the German Welding Society (DVS), which have general acceptance on the European level.

#### Basic conditions

The welding area shall be shielded from unfavourable weather (e.g. humidity, wind, excessive sunlight, or temperatures below 0°C). If the pipe accumulates local heat from direct sunlight, the weld area should be covered early enough to bring the temperature down.

The mating fusion surfaces of the components to be welded must not be damaged and must be free of contamination (e.g.



4.40 Principle of butt fusion welding

dirt, grease, chips). The fusion surfaces shall be cleaned directly before welding. As pipes may show ovalities after storage, it may be necessary to restore the shape of the pipe ends, e.g. by means of a re-rounding tool. End caps on the delivered pipes shall not be removed until immediately before the welding operation and then only at the ends to be welded.

All tools and pieces of equipment mentioned in the following instructions are available as Gerodur accessories (→ Accessories, p. 309). The welding report (tem-

plate → p. 321) and the specified welding parameters (→ table 4.49, p.143) shall be used to ensure proper performance of the procedure.


### Work instructions according to DVS 2207-1 (HS)

1. Set up appropriate work conditions, e.g. a welding tent. → Fig. 4.42
2. Connect the welding device to the power mains or to a generating set and check its function.
3. Do not remove the end cap (delivered condition) from the pipe end opposite to the fusion end to avoid air draught.
4. Align and clamp the components to be welded. For pipes having a protection jacket, use appropriate inserts with a clamp size adapted to jacketed pipes. → Fig. 4.43
5. Smoothen the jointing surfaces of the pipes with a planing tool (blades must be sharp!). Then remove the tool and eliminate all shavings and chips from the welding zone. → Fig. 4.44
6. Check the planed jointing surfaces to make sure they are parallel. Check for offset (max. 0.1 x wall thickness) → Fig. 4.45  
The allowable joint clearance is shown in the following table:

DN/OD	Allowable clearance
≤ 355mm	≤ 0.5mm
< 630mm	≤ 1.0mm

4.41 Allowable clearance (DVS 2207-1)

7. Check the temperature of the heater plate before starting to weld. To do so, use an instant-read instrument suitable for surface temperature measurements. Guide value for PE100: 220°C.
8. Clean the heater plate with a non-linting and non-coloured paper.
9. Read the drag pressure or drag force on the welding machine and record the value in the welding report.




4.42 Set up and maintain appropriate work conditions


10. Determine the settings for the bead-up and jointing pressures, or the jointing force based on the guide value of 0.15 N/mm<sup>2</sup> for PE-HD pipe. The heat-soak pressure is 0.01 N/mm<sup>2</sup>.

$$\begin{aligned} & \text{Jointing pressure (acc. to machine parameters)} \\ & + \text{ Drag pressure (setting)} \\ & \hline = & \text{ Bead-up or jointing pressure} \end{aligned}$$


11. All guide values (e.g. heat-soak time, jointing pressure or jointing force etc...) must be defined accordingly.



4.43 Clamp the pipes using clamp inserts for jacketed pipes



4.44 Planing




4.45 Check visually for offset and joint clearance

- Where necessary, clean the fusion surfaces with an approved cleansing agent (e.g. PE cleaner) and paper in accordance with the following requirements. → Fig. 4.46

The cleansing agent, incl. the cleansing agent used for ready-made wetted cloths delivered by the manufacturer in a locking plastic box, must be composed of 100% volatilising solvent, e.g. 99 parts of ethanol with 99.8% purity and one part of MEK (methyl ethyl ketone, denaturing). Cleansing agents certified to DVGW V 603 fulfil these requirements. The safety data sheet (SDS) of the cleansing agent shall be observed. The wiping paper must be clean, first use, absorbent, unscented, non-linting and non-coloured.

- Place the heater plate into welding position.
- Match the fusion ends with the heater plate until sufficient bead width. → Fig. 4.47
- Heat the fusion surfaces at reduced pressure (heat-soak time: 10 seconds per 1 mm wall thickness). Then remove the heater plate from between the joining ends (change-over).




4.46 Remove chips and shavings in the joining area and clean the fusion surfaces with PE cleaner


- Bring together the molten ends within the changeover period (heater plate removal time). The velocity at contact must be near zero (as low as possible). Immediately join the molten ends continuously within the force build-up time until the required jointing force or required jointing pressure is reached. A proper weld will form a post-fusion bead ( $K > 0$  according to DVS 2207-1). → Fig. 4.48

**! A properly executed weld is in the utility core pipe material only, visible as a continuous black bead of core pipe material.**

- Maintain the jointing force until the weld has cooled down.
- After the cooling phase, unclamp the jointed components and complete the welding report.



4.47 Initial bead-up and heat soak



4.48 Changeover, jointing and final cooling under jointing pressure


Nominal wall thickness	Bead-up	Heat soak	Changeover	Joining	
	Forming a specified bead size at end of initial bead-up time (minimum values) $p=0.15\text{N/mm}^2$	Heat-soak time = 10 sec per 1 mm wall thickness $p\leq 0.01\text{N/mm}^2$	Heater plate removal time (maximum duration)	Joining force build-up time	Cooling time under joining pressure* (minimum values) $p=0.15\text{N/mm}^2$
[mm]	[mm]	[s]	[s]	[s]	[min]
$\leq 4.5$	0.5	$\leq 45$	5	5	6.5
4.5–7	1.0	45–70	5–6	5–6	6.5–9.5
7–12	1.5	70–120	6–8	6–8	9.5–15.5
12–19	2.0	120–190	8–10	8–11	15.5–24
19–26	2.5	190–260	10–12	11–14	24–32
26–37	3.0	260–370	12–16	14–19	32–45
37–50	3.5	370–500	16–20	19–25	45–61
50–70	4.0	500–700	20–25	25–35	61–85

6.49 Benchmarks for butt fusion welding according to DVS 2207-1 | \* Ambient temperature of 25–40°C | Guide values applicable to GEROfit®R pipes between 25 and 40°C and at moderate movement of the air. At lower ambient temperatures, the cooling time acc. to DVS 2207-1 can be reduced. The heater plate temperature guide value is 220°C. Changeover time must be kept as short as possible to avoid impairment of weld quality.

## Electrofusion (HM)

The fusion surfaces (external surfaces of the core pipe and internal surface of the electrofusion fitting) are electrically heated via heater coils integrated in the fitting and the fitting is welded to the pipe under fusion pressure. The automatic welding operation shall be carried out with appropriate equipment adapted to the fitting. Also, the manufacturer's information and instructions shall be observed. For GEROfit®R the protection jacket needs to be removed by means of a suitable jacket peeling tool (GEROfit®pocket or pocket XL) over the following lengths:

Jacket removal length LS =  
fitting insertion depth + 10 mm (guide value)



4.50 Principle of electrofusion welding

### Basic conditions

The welding area shall be shielded from unfavourable weather (e. g. humidity, wind, excessive sunlight, or temperatures below 0°C). If the pipe accumulates local heat from direct sunlight, the weld area should be covered early enough to bring the temperature down. Care shall be taken to maintain the pipe and the electrofusion fitting at almost identical temperature. The mating fusion surfaces of the components to be jointed

must not be damaged and must be free of contamination (e. g. dirt, grease, chips). As pipes may show ovalities after storage, it may be necessary to restore the shape of the pipe ends, e. g. by means of a re-rounding tool. End caps on the delivered pipes shall not be removed until immediately before the welding operation and then only at the ends to be welded. The mating surfaces of the pipe and electrofusion fitting shall be cleaned directly before welding.

All tools and pieces of equipment mentioned in the following instructions are available as Gerodur accessories (→ Accessories, p. 309).

An appropriate welding report (template → p. 322) shall be used to ensure proper performance of the procedure.

**Work instructions according to DVS 2207-1 (HM)**


1. Set up appropriate work conditions, e.g. a welding tent. → Fig. 4.51
2. Connect the welding device to the power mains or to a generating set and check its function.
3. Remove the protection jacket from the square-cut pipe ends (→ handling of jacket peelers, p. 147 et seq.) and remove burr from the external surface. (For tapping clamps or weld-on saddles, remove the protection jacket to ensure the saddle is welded onto the PE100-RC core pipe.) → Fig. 4.52
4. Where necessary, use re-rounding clamps to restore the circularity of the pipe ends. Allowable ovality is 1.5 %, but no more than 3 mm.
5. Remove the oxidised layer on the pipe surface with a rotary peeling tool (hand scraper in exceptional cases only) at constant depth of about 0.2 mm. → Fig. 4.53
6. Remove the electrofusion fitting from the original package.

7. Clean the peeled pipe surface and internal fitting surface with an approved cleansing agent (e.g. PE cleaner) and paper in accordance with the following requirements. → Fig. 4.54


The cleansing agent, incl. the cleansing agent used for ready-made wetted cloths delivered by the manufacturer in a locking plastic box, must be composed of 100 % volatilising solvent, e.g. 99 parts of ethanol with 99.8 % purity and one part of MEK (methyl ethyl ketone, denaturing). Cleansing agents certified to DVGW VP 603 fulfil these requirements. The safety data sheet (SDS) of the cleansing agent shall be observed. The wiping paper must be clean, first use, absorbent, unscented, non-linting and non-coloured.

8. Indicate the insertion depth with a visible mark on the pipe.
9. Insert the pipe end into the fitting without applying force. Make sure the ends are square and parallel, and secure the assembly.
10. Plug the cable of the welding machine into the fitting contacts by ensuring sufficient stress relief.


**! Make sure the insertion depth is correct and the assembly is stressfree; use a restraining device. (The tapping clamps or weld-on saddles shall be secured on the pipe surface with a restraining device!).**




4.51 Set up and maintain appropriate work conditions




4.52 Remove the protection jacket in good workmanship



4.54 Clean the fusion surfaces with PE cleaner



4.53 Machine the weld area, reliable with rotary peeler



4.55 Scan the parameters (bar code), then weld and observe the cooling time

11. Check the settings or data indicated on the display as appropriate. Enter or scan the welding data into the machine. → Fig. 4.55
12. Perform or check the welding process according to the manufacturer's instructions.
13. Unplug the cable from the fitting.
14. Observe the cooling time specified by the manufacturer, then unclamp the retaining device (not required for certain tapping clamps with integrated holder – refer to the manufacturer's instructions).
15. If no automatic report is issued, draft a manual welding report.

## Special requirements

The following is a brief summary of special requirements applicable to butt fusion welds according to DVS 2207-1:

- The weld area must be protected from unfavourable weather impacts, such as:
  - Moisture, snow, hoarfrost, etc.
  - Ambient temperature below 0°C
  - Wind
  - Extended exposure to sunlight
- Welding at temperatures below 0°C is possible under the mentioned conditions when a sufficient pipe wall tempera-

ture is guaranteed by tenting, warming-up, heating, without impairing the manual skills of the welder.

- Under the mentioned conditions, it may be necessary to perform test welds to provide additional proof of suitability.
- A uniform temperature level shall be maintained for the pipes and fittings to be welded.
- Pipes, fittings and pipe components must have the same SDR for welding (exception: SDR 17.6 with SDR 17).

## Further information

After correct welding, the external weld bead can be incised and stripped off along the entire circumference at the end of the prescribed cooling time, either by hand or with pliers. (The removal of the external bead is prescribed for DVGW GW 323 no-dig renewal by pipe bursting.)

Welding operations need to be supervised according to GW 331 or DVS 2212-1 (Supplement 1). It is strongly advised to perform the welds in compliance with DVS 2207-1 and to

use welding equipment meeting the requirements laid down in guideline DVS 2208-1, or to work in accordance with national guidelines conforming thereto.

It is recommended to record the welding data of the different job sections separately by nominal diameters. For welding report templates according to DVS 2207-1, → Appendix, p. 321 et seq.

## Use of tapping fittings

For valve drilling fittings with sealing sleeve (system EWE for potable water) and weld-on tapping fittings, it is imperative to remove the protection jacket with the GEROfit®pocket or pocket XL jacket peeler. The welding operation shall comply with DVS 2207 (Part 1) while observing the fitting manufacturers' instructions.

### Procedure

1. Mark the jacket section to be stripped on both sides according to the dimension of the tapping fitting plus 10 mm.
2. Remove the protection jacket using the GEROfit®pocket or pocket XL jacket peeler (→ handling of jacket peelers, p. 147 et seq.).
3. Prepare the pipe surface and remove the oxidised layer.
4. Then install the fitting.
5. Welding shall conform to DVS 2007.

## Other jointing technologies

### Clamped, bolted, socket and pressed joints

When using clamped, bolted, socket-type or pressed joints, it is required to remove the protection jacket according to the insertion depth. We recommend exclusive use of products approved by DVGW for PE-HD pipes. The manufacturer's instructions shall be complied with.

### Flanged joints

Flanged connections shall be performed with corresponding stub ends (long – electrofusion, short – butt fusion).

Stub ends shall have the same SDR class as the pipes. The backing rings must match the given pressure rating. The flange manufacturer's instructions shall be complied with.



4.56 Tapping fittings for manhole connection



4.57 Re-rounding clamps for EF joints (source: +GF+)

PE pipes tend to flatten during storage. If ovality in the weld area is  $> 1.5\%$  of the DN/OD or  $\geq 3.0\text{mm}$ , the pipes must be re-rounded with an appropriate tool (re-rounding clamps). The mounting instructions of the joint manufacturers must be complied with.

### 3.4 Handling of jacket peelers

The GEROfit®pocket and pocket XL jacket peelers are specially adapted to strip off dimensionally added and peelable protection jackets from PE pipes. Jacket removal procedures vary depending on products or manufacturers. The present instructions are solely focused on the peeler tool. For a detailed description of the individual work steps and particularities of a specific pipe, it is imperative to consult and observe the separate instructions of the pipe manufacturer and, where necessary, fitting manufacturer.

The peeler can be used both in industrial shops and on construction sites. The work area must always be kept clean. Chips, shavings or dirt can impair the function of the tool. The peeling knife and the moving parts shall be cleaned as described herein; oil the tool as appropriate (precision engineering oil).

**Important:**

All work must conform to currently applicable safety rules to ensure personal safety both for oneself and other persons. Improper use can cause injuries or damage the product/pipe in a way to reduce its service life or even destroy it.

The tool is not suitable for other uses like opening tin cans – very high risk of injury!

We recommend that the peeler should be kept in the original tool box or bag after usage.

Gerodur jacket peelers are available in two sizes (→ Accessories, p. 309):

**GEROfit® pocket jacket peeler**

DN/OD 32 – 160 mm

**GEROfit® pocket XL jacket peeler**

DN/OD 160 – 630 mm

There is no difference in handling.

The stripping width or cutback dimension (D) of the zone to be peeled off shall be selected according to the dimensional data provided by the manufacturer of the fitting.

**Peeling for Type 3 jacketed pipe acc. to PAS 1075**

*At end of pipe*

1. Use the setscrew (A) to adjust the cutting depth to the given jacket thickness (0–6 mm). → Fig. 4.58
2. Mark the stripping width (D) before starting to cut. → Fig. 4.59
3. Move the lever (B) while holding down the toothed wheel to slit the protection jacket open. Each time when starting a lengthwise (axial) or circular (radial) cut, guide the knife by pressing it slightly down with your finger (C). → Fig. 4.60

**! A cutting depth setting in excess of the jacket thickness can damage the core pipe.**

4. The peeler can be turned by 90 degrees between a lengthwise (axial) cut and a circular (radial) cut. → Fig. 4.61
5. After cutting, the jacket can be easily removed (for larger pipe sizes it may be necessary to use pliers for stripping off the jacket). → Fig. 4.62
6. Check for integrity of the pipe surface.

*Between pipe ends*


(same settings as described above)

7. Mark the dimensions of the jacket section to be cut out (e.g. with an indelible marker).
8. Press the tip of the cutting knife into the pipe jacket to cut out an "intermediate length" (e.g. for saddle). → Fig. 4.63


**! Before proceeding to the next operation, check the surface of the core pipe. Damaged pipe sections must be cut off.**

*Spare knife/knife change*


The knife can be changed by turning (opening/closing) the setscrew (A). → Fig. 4.64




4.58 Adjust the cutting depth with the setscrew




4.59 Measure the distance from the pipe end




4.62 Strip off the jacket




4.60 Lengthwise cut along the pipe axis



4.63 Cut and strip off the jacket between pipe ends



4.61 Radial cut in parallel with the pipe end



4.64 How to replace the knife